

PASY OKRĄGLE

TYLKO WYMIARY CALOWE

ŚREDNICA mm (cale)	80A -40°C do 55°C 0.55 TAK		80A -40°C do 55°C 0.55 TAK		83A -40°C do 55°C 0.55 TAK		83A -40°C do 55°C 0.55 TAK		88A -30°C do 80°C 0.38 NIE		88A -30°C do 80°C 0.40 NIE	
	MŚK (mm)	SP (1%)	MŚK (mm)	SP (1%)	MŚK (mm)	SP (1%)	MŚK (mm)	SP (0.3%)	MŚK (mm)	SP (1%)	MŚK (mm)	SP (1%)
2	15	0.06	15	0.06	15	0.06			19	0.13		
3 (1/8)	20	0.14	20	0.14	20	0.14			29	0.31		
4	30	0.25	30	0.25	30	0.25			38	0.54		
5 (3/16)	35	0.40	35	0.40	34	0.40			48	0.85		
6			38	0.55					57	1.22		
6.3 (1/4)	40	0.60	40	0.60	38	0.68	42	4.5				
7									67	1.67	70	18
8 (5/16)	55	1.00	55	1.00	48	1.06	54	5	76	2.18	80	19
9									86	2.75	90	21
9.5 (3/8)	65	1.40	65	1.40	57	1.54	64	9.5				
10			70	1.55					95	3.40	100	22
12									114	4.90	120	26
12.5 (1/2)	85	2.50	85	2.45	75	2.72	86	11.4				
14 (9/16)					84	3.43	95	12.3				
15 (5/8)	100	3.50	100	3.50	95	4.25	108	13.6	143	7.65	150	27
18	120	5.10	120	5.10					171	11.00	180	37
19 (3/4)					115	6.11	127	15				
20									190	13.60		
25					150	10.6						

90A -30°C do 60°C 0.45 TAK		95A -30°C do 60°C 0.36 TAK		100A -20°C do 75°C 0.27 TAK		100A -20°C do 75°C 0.28 TAK	
MŚK (mm)	SP (1%)	MŚK (mm)	SP (1%)	MŚK (mm)	SP (1%)	MŚK (mm)	SP (1%)
20	0.26					40	0.6
30	0.60					60	1.4
40	1.00					80	2.5
50	1.60					100	3.9
60	2.60	75	20	100	25	125	6.2
80	4.20	95	35			160	10
95	5.90	110	37	150	40	190	14
125	10.10	150	57	200	42	250	16
150	14.60	175	60			300	23
180	21.00	210	64			360	34
200	25.90						

